



**Dominion**

# **DAM INSPECTION CHECKLIST POSSUM POINT POWER STATION POND ABC**

INSPECTION DATE: 5/18/15

WEATHER: 82°F, Few clouds,

INSPECTED BY: D. West, K. Homza

Location/ Condition	(y/n)	Change (y/n)	Comments
Low Point, A dike*			
Flow	N	N	1335 hrs. Standing water along perimeter of pond
Erosion	N	N	near road. Small amount of stagnant standing water
Low Point, B dike*			
Flow	N	N	1337 hrs. Sandbags and rip rap in place. No
Erosion	N	N	standing water.
Outfall water surface El. (top of stoplogs to water)			1343 hrs. Standing water behind concrete weir structure. 43". Standing water behind sandbags. No seep or flow into discharge pipe.

behind  
sandbags.

\* See figure below.

Additional Comments (Note any changes observed along the embankment crest or downstream slope observed from the crest.): Rainfall event of 1.14" ending ~ 1400 on 5/17/15. Standing water at the base of the slope between A and B pond.

LT: 1410hrs HT: 2015 hrs

